

Wine Bottle Platter Firing Schedule

This is the schedule that I use to flatten wine bottles for serving platters for a local winery.



Seg	DPH	Temp	Hold
1	300	1000	0
2	1000	1395	20
3	AFAP	1000	5
4	200	950	55
5	200	800	0

Total running time: 6.7 hours. approx. Dumping heat at 1395 may alter time. This schedule works well for green glass which is softer. For clear glass you will have to increase the time, temperature or both. Clear glass is much harder than green glass.